	Туре	Hits	Search Text
1	BPS	:02	rkerf; and thip
2	BRS	57	438/\$.ccls. and ((kerf) with (chip);
3	BRS	0	438/\$.ccls. and ((kerf) with (chip)) and (saw\$3) and (etch\$3) and (ion adj beam adj mil\$4)
4	BRS	0	438/\$.ccls. and ((kerf) with (chip)) and (saw\$3) and (etch\$3) and (ion adj beam adj mill\$3)
5	BRS	10	438/\$.ccls. and ((kerf) with (chip)) and (saw\$3) and (etch\$3)
6	BRS	135	438/\$.ccls. and :(slit or cur) with (chip)) and (saw\$3) and etch\$5;
7	BRS	26	438/\$.ccls. and ((remove\$3) with (ion adj beam adj milling))
8	BRS	25	438/\$.ccls. and ((remove\$3) with (ion adj beam adj milling))

DBs	Time Stamp	Comments	Error Definition	
USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2002/11/07 12:44			
USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2002/11/07 12:45			
USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2002/11/07 12:48	*	Truncation were low.	
USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2002/11/07 12:48	<u>.</u>	<u></u>	
USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2002/11/07 13:05)		
USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2002/11/07 15:27	7		
USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2002/11/07 15:36	5		
USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/11/07 15:30	6		

	Errors
	0
2	0
3	1
4	0
5	0
ϵ	С
7	С
8	0